


DISPLAY ACCESSORIES 4 BROCHURE



01 Clip support foot on to the centre of the bottom aluminum profile.




02 Assemble & join 3-piece pole sections.



03 Insert pole assembly into support foot.



04 Bend pole forward and insert clip into the centre of the upper aluminum profile.



05 Assembly is complete.

